



## INFORMATION BULLETIN

Bulletin n°05-2005 - Level : =>

### Correct Installation of the Kuntzleman Strobe (SC 103)

#### Explanation of symbols:

-  **DANGER** Identifies an Instruction which, if it is not observed, can have **fatal** consequences.
-  **ATTENTION** Identifies an Important Instruction which, if not followed, can cause very **serious damage**
- =>** **INFORMATION** Identifies Significant Information

**Concern:** Kuntzleman Strobe Assembly (SC 103).

**Problem:** On two (2) aircraft, a fracture of the lower radiator strut as been observed upon which a Kuntzleman strobe was attached.

**Cause:** Incorrectly installed and situated strobe mount.

**Solution:** The strobe must be installed **UNDER** the radiator strut (See Illustration A).

**Note:** Observe the stacking order illustrated in the photograph below.

**Reminder:** The strobe's stainless attachment bracket angle **MUST** not be changed; it is imperative that the cap screw **NOT** be loosened. This screw also fixes the internal board which contains the electronic components.

Illustration A

